



Photo 1: Landscape of the investigated area



Photo 2: Head slope of a Type-G channel head (O16H)





Photo 3: A channel head of Type S (O38H)

The property of this channel head cannot be precisely measured in situ because of steepness



Photo 4: The channel head in C1 watershed (C1H)





Photo 5: The channel head in C3 watershed (C3H)



Photo 6: A bedload trap and a flume at C1L site





Photo 7: A bedload trap and a flume at C3U site

Photograph was taken during a storm runoff on 9 July 2000.



Photo 8: A bedload trap and a flume at C3L site





Photo 9: A rockfall trap at R-1 site in C3 watershed



Photo 10: The bedload trap torn by debris at C3U site

Photograph was taken on 1 September 2001.





Photo 11: The debris captured in the flume at C3U site

Photograph was taken on 1 September 2001.